

Report on Animal Shelter's "SECOND HOME" building construction progress.

(I) General overview		
Nº	Work	Progress stage (done, started, almost done)
I. General construction works		
1.	Demolition	Done
2.	Foundation	Done
3.	Walls, parting wall	Done
4.	Roof	Done
5.	Façade	Done
6.	Apertures	Done
7.	Internal finishing works	Almost done
II. Internal specialized works		
8.	Internal water supply U1; S3. Internal domestic sewerage K1	Done
9.	Heating system	Done
10.	Boiler/mechanical room	Done
11.	Ventilation	Done
12.	Electric power system	Done
13.	Automatic fire-fighting system	Done
III. External engineering		
14.	External drainage K	
IV. Special works and structure		
15.	Staircases, porch & ramp	Done
16.	Road, parking, planting of greenery	Almost done

Photo evidence

Ground floor

Internal works in progress:

Isolation room



WC – ground floor



Grooming room – ground floor



Kitchen ground floor



Main Corridor



Entrance/Reception Corridor



Storage/Laundry room



Here you can also see donated washing machine.







Boiler room



Internal works on **first floor** in progress:







Porch & ramp



How the building looks NOW (9th of July, 2018)

First floor/attics:

Puppy room



Kitchen



Bathroom/WC




Office



Education room



Room for sleep over



Corridor



Started stairs to first floor and façade

